

1. Name of Reporting Railroad Union Pacific Railroad Company [UP]				1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0916LA012	
2. Name of Other Railroad or Other Entity Filing for Equipment Involved in Train Accident/Incident				2a. Alphabetic Code		2b. Railroad Accident/Incident No.	
3. Name of Railroad or Other Entity Responsible for Track Maintenance (single entry) Union Pacific Railroad Company [UP]				3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. 0916LA012	
4. U.S. DOT Grade Crossing ID No. 811074G				5. Date of Accident/Incident month day year 0 9 2016		6. Time of Accident/Incident 1:42 AM <input checked="" type="checkbox"/> PM <input type="checkbox"/>	
7. Nearest Railroad Station MONTEBELLO		8. Subdivision LOS ANGELES SUB		9. County LOS ANGELES		10. State Abbr. CA Code 06	
11. City (if in a city) MONTEBELLO			12. Highway Name or No. MONTEBELLO BLVD			Public <input checked="" type="checkbox"/> Private <input type="checkbox"/>	
Highway User Involved				Rail Equipment Involved			
13. Type C. Truck-trailer F. Bus J. Other Motor Vehicle A. Auto D. Pick-up truck G. School Bus K. Pedestrian Code B. Truck E. Van H. Motorcycle M. Other (specify) K				17. Equipment 1. Train (units pulling) 2. Train (units pushing) 3. Train (standing) 4. Car(s) (moving) 5. Car(s) (standing) 6. Light loco(s) (moving) 7. Light loco(s) (standing) 8. Other (specify) A. Train pulling- RCL B. Train pushing- RCL C. Train standing- RCL D. EMU Locomotive(s) E. DMU Locomotive(s) Code 1			
14. Vehicle Speed (est. mph at impact)		15. Direction (geographical) 1. North 2. South 3. East 4. West Code 3		18. Position of Car Unit in Train 1			
16. Position 1. Stalled or stuck on crossing 2. Stopped on Crossing 3. Moving over crossing 4. Trapped on crossing by traffic 5. Blocked on crossing by gates Code 3				19. Circumstance 1. Rail equipment struck highway user 2. Rail equipment struck by highway user Code 1			
20a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code 2				20b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code 4			
20c. State here the name and quantity of the hazardous material released, if any							
21. Temperature (specify if minus) 69 °F		22. Visibility (single entry) 1. Dawn 2. Day 3. Dusk 4. Dark Code 4		23. Weather (single entry) 1. Clear 2. Cloudy 3. Rain 4. Fog 5. Sleet 6. Snow Code 1			
24. Type of Equipment (single entry) 1. Freight Train 2. Passenger Train-Pulling 3. Commuter Train-Pulling 4. Work Train 5. Single Car 6. Cut of cars 7. Yard/Switching 8. Light loco(s) 9. Maint./inspect. car A. Spec. MoW Equip. B. Passenger Train-Pushing C. Commuter Train-Pushing D. EMU E. DMU Code 1				25. Track Type Used by Rail Equipment Involved 1. Main 2. Yard 3. Siding 4. Industry Code 1		26. Track Number or Name NO 2 MAIN	
27. FRA Track Class (1-9,X) 5		28. Number of Locomotive Units 3		29. Number of Cars 124		30. Consist Speed (Recorded speed if available) R. Recorded E. Estimated 33 mph Code R	
31. Time Table Direction 1. North 2. South 3. East 4. West Code 3				32. Type of Crossing Warning 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (specify) 12. None Code(s) 01 03 06 07			
33. Signaled Crossing Warning (See reverse side for instructions and codes) Code 2				34. Roadway Conditions A. Dry B. Wet C. Snow/Slush D. Ice E. Sand, Mud, Dirt, Oil, Gravel F. Water (Standing, Moving) Code A			
35. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach Code 1			36. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown Code 1			37. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown Code 1	
38. Highway User's Age 62		39. Highway User's Gender 1. Male 2. Female Code 2		40. Highway User Went Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code 2		41. Highway User 1. Went around the gate 2. Stopped and then proceeded 3. Did not stop 4. Stopped on crossing 5. Other (specify) 6. Went around/thru temporary barricade (if yes, see instructions) 7. Went thru the gate 8. Suicide/Attempted suicide Code 8	
42. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown Code			43. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing railroad equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicles 7. Other (specify) 8. Not Obstructed Code 8				
Casualties to:		Killed		Injured		44. Driver was 1. Killed 2. Injured 3. Uninjured	
46. Highway-Rail Crossing Users 1		0		47. Highway Vehicle Property Damage (est. dollar damage)		45. Was Driver in the Vehicle? 1. Yes 2. No	
49. Railroad Employees 0		0		50. Total Number of People on Train (include passengers and train crew) 2		48. Total Number of Vehicle Occupants (including driver) 0	
52. Passengers on Train 0		0		51. Is a Rail Equipment Accident / Incident Report Being Filed 1. Yes 2. No Code 2			
53a. Special Study Block Video Taken? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Video Used? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No				53b. Special Study Block			
54. Narrative Description (Be specific, and continue on separate sheet if necessary) PEDESTRIAN WAS WALKING EAST ON THE CROSSING AFTER GOING AROUND THE ACTIVATED GATES. TRAIN BLEW THE WHISTLE AND SHE LOOKED BACK AT THEM WHILE SHE KEPT WALKING AND WAS STRUCK.							
55. Typed Name and Title				56. Signature		57. Date	

NOTE: This report is part of the reporting railroad's accident report pursuant to the accident reports statute and, as such shall not "be admitted as evidence or used for any purpose in any suit or action for damages growing out of any matter mentioned in said report..." 49 U.S.C. 20903. See 49 C.F.R. 225.7 (b).

1. Name of Reporting Railroad Union Pacific Railroad Company [UP]				1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 1013LA012	
2. Name of Other Railroad or Other Entity Filing for Equipment Involved in Train Accident/Incident				2a. Alphabetic Code		2b. Railroad Accident/Incident No.	
3. Name of Railroad or Other Entity Responsible for Track Maintenance (single entry) Union Pacific Railroad Company [UP]				3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. 1013LA012	
4. U.S. DOT Grade Crossing ID No. 811074G				5. Date of Accident/Incident month day year 1 0 1 9 2013		6. Time of Accident/Incident 3:35 AM <input checked="" type="checkbox"/> PM <input type="checkbox"/>	
7. Nearest Railroad Station MONTEBELLO		8. Subdivision LOS ANGELES SUB		9. County LOS ANGELES		10. State Abbr. CA Code 06	
11. City (if in a city) MONTEBELLO				12. Highway Name or No. MONTEBELLO BLVD Public <input checked="" type="checkbox"/> Private <input type="checkbox"/>			
Highway User Involved				Rail Equipment Involved			
13. Type C. Truck-trailer F. Bus J. Other Motor Vehicle A. Auto D. Pick-up truck G. School Bus K. Pedestrian Code B. Truck E. Van H. Motorcycle M. Other (specify) A				17. Equipment 1. Train (units pulling) 2. Train (units pushing) 3. Train (standing) 4. Car(s) (moving) 5. Car(s) (standing) 6. Light loco(s) (moving) 7. Light loco(s) (standing) 8. Other (specify) A. Train pulling- RCL B. Train pushing- RCL C. Train standing- RCL D. EMU Locomotive(s) E. DMU Locomotive(s) Code 1			
14. Vehicle Speed (est. mph at impact) 0		15. Direction (geographical) 1. North 2. South 3. East 4. West Code 1		18. Position of Car Unit in Train 1			
16. Position 1. Stalled or stuck on crossing 2. Stopped on Crossing 3. Moving over crossing 4. Trapped on crossing by traffic 5. Blocked on crossing by gates Code 1				19. Circumstance 1. Rail equipment struck highway user 2. Rail equipment struck by highway user Code 1			
20a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code 4				20b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code 4			
20c. State here the name and quantity of the hazardous material released, if any							
21. Temperature (specify if minus) 61 °F		22. Visibility (single entry) 1. Dawn 2. Day 3. Dusk 4. Dark Code 4		23. Weather (single entry) 1. Clear 2. Cloudy 3. Rain 4. Fog 5. Sleet 6. Snow Code 1			
24. Type of Equipment (single entry) 1. Freight Train 2. Passenger Train-Pulling 3. Commuter Train-Pulling 4. Work Train 5. Single Car 6. Cut of cars 7. Yard/Switching 8. Light loco(s) 9. Maint./inspect. car A. Spec. MoW Equip. B. Passenger Train-Pushing C. Commuter Train-Pushing D. EMU E. DMU Code 1				25. Track Type Used by Rail Equipment Involved 1. Main 2. Yard 3. Siding 4. Industry Code 1		26. Track Number or Name NO 1 MAIN	
27. FRA Track Class (1-9,X) 4		28. Number of Locomotive Units 3		29. Number of Cars 92		30. Consist Speed (Recorded speed if available) R. Recorded 45 mph E. Estimated Code E	
31. Time Table Direction 1. North 2. South 3. East 4. West Code 3				32. Type of Crossing Warning 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (specify) 12. None Code(s) 01 03 06 07			
33. Signaled Crossing Warning (See reverse side for instructions and codes) Code 1				34. Roadway Conditions A. Dry B. Wet C. Snow/Slush D. Ice E. Sand, Mud, Dirt, Oil, Gravel F. Water (Standing, Moving) Code A			
35. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach Code 1				36. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown Code 1		37. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown Code 2	
38. Highway User's Age 23		39. Highway User's Gender 1. Male 2. Female Code 1		40. Highway User Went Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code 2		41. Highway User 1. Went around the gate 2. Stopped and then proceeded 3. Did not stop 4. Stopped on crossing 5. Other (specify) 6. Went around/thru temporary barricade (if yes, see instructions) 7. Went thru the gate 8. Suicide/Attempted suicide Code 4	
42. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown Code 2				43. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing railroad equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicles 7. Other (specify) 8. Not Obstructed Code 8			
Casualties to:		Killed		Injured		44. Driver was 1. Killed 2. Injured 3. Uninjured Code 3	
46. Highway-Rail Crossing Users 0		1		47. Highway Vehicle Property Damage (est. dollar damage) \$10,000		45. Was Driver in the Vehicle? 1. Yes 2. No Code 2	
49. Railroad Employees 0		0		50. Total Number of People on Train (include passengers and train crew) 2		48. Total Number of Vehicle Occupants (including driver) 1	
52. Passengers on Train 0		0		51. Is a Rail Equipment Accident / Incident Report Being Filed 1. Yes 2. No Code 2			
53a. Special Study Block Video Taken? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Video Used? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				53b. Special Study Block			
54. Narrative Description (Be specific, and continue on separate sheet if necessary) HIGHWAY USER'S ACTIONS: STOPPED ON CROSSING (BEFORE GATES DESCENDED). INJURY TO A PASSENGER WAS REPORTED WHO WAS STILL INSIDE THE VEHICLE AT THE TIME OF IMPACT.							
55. Typed Name and Title				56. Signature		57. Date	

1. Name of Reporting Railroad Southern California Regional Rail Authority [SCAX]				1a. Alphabetic Code SCAX		1b. Railroad Accident/Incident No. 94272013	
2. Name of Other Railroad or Other Entity Filing for Equipment Involved in Train Accident/Incident				2a. Alphabetic Code		2b. Railroad Accident/Incident No.	
3. Name of Railroad or Other Entity Responsible for Track Maintenance (single entry) Union Pacific Railroad Company [UP]				3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. XXX	
4. U.S. DOT Grade Crossing ID No. 811074G				5. Date of Accident/Incident month day year 0 9 2 8 1994		6. Time of Accident/Incident 1:18 AM <input type="checkbox"/> PM <input checked="" type="checkbox"/>	
7. Nearest Railroad Station LOS ANGELES UNION ST			8. Subdivision		9. County LOS ANGELES		10. State Abbr. CA Code 06
11. City (if in a city) MONTEBELLO			12. Highway Name or No. MONTEBELLO AVE (8.5) Public <input checked="" type="checkbox"/> Private <input type="checkbox"/>				
Highway User Involved				Rail Equipment Involved			
13. Type C. Truck-trailer F. Bus J. Other Motor Vehicle A. Auto D. Pick-up truck G. School Bus K. Pedestrian Code B. Truck E. Van H. Motorcycle M. Other (specify) K				17. Equipment 1. Train (units pulling) 2. Train (units pushing) 3. Train (standing) 4. Car(s) (moving) 5. Car(s) (standing) 6. Light loco(s) (moving) 7. Light loco(s) (standing) 8. Other (specify) A. Train pulling- RCL B. Train pushing- RCL C. Train standing- RCL D. EMU Locomotive(s) E. DMU Locomotive(s) Code 1			
14. Vehicle Speed (est. mph at impact) 0		15. Direction (geographical) 1. North 2. South 3. East 4. West Code 1		18. Position of Car Unit in Train 1			
16. Position 1. Stalled or stuck on crossing 2. Stopped on Crossing 3. Moving over crossing 4. Trapped on crossing by traffic 5. Blocked on crossing by gates Code 2				19. Circumstance 1. Rail equipment struck highway user 2. Rail equipment struck by highway user Code 1			
20a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code 4				20b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code			
20c. State here the name and quantity of the hazardous material released, if any							
21. Temperature (specify if minus) 90 °F		22. Visibility (single entry) 1. Dawn 2. Day 3. Dusk 4. Dark Code 2		23. Weather (single entry) 1. Clear 2. Cloudy 3. Rain 4. Fog 5. Sleet 6. Snow Code 1			
24. Type of Equipment (single entry) 1. Freight Train 2. Passenger Train-Pulling 3. Commuter Train-Pulling 4. Work Train 5. Single Car 6. Cut of cars 7. Yard/Switching 8. Light loco(s) 9. Maint./inspect. car A. Spec. MoW Equip. B. Passenger Train-Pushing C. Commuter Train-Pushing D. EMU E. DMU Code 2				25. Track Type Used by Rail Equipment Involved 1. Main 2. Yard 3. Siding 4. Industry Code 1		26. Track Number or Name SINGLE MAIN TRACK	
27. FRA Track Class (1-9,X) 4		28. Number of Locomotive Units 1		29. Number of Cars 4		30. Consist Speed (Recorded speed if available) R. Recorded 68 mph E. Estimated Code E	
31. Time Table Direction 1. North 2. South 3. East 4. West Code 3				32. Type of Crossing Warning 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (specify) 12. None Code(s) 01 06 07			
33. Signaled Crossing Warning (See reverse side for instructions and codes) Code 1				34. Roadway Conditions A. Dry B. Wet C. Snow/Slush D. Ice E. Sand, Mud, Dirt, Oil, Gravel F. Water (Standing, Moving) Code			
35. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach Code 2			36. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown Code 3			37. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown Code 3	
38. Highway User's Gender 1. Male 2. Female Code 1		39. Highway User's Age 1. Male 2. Female Code		40. Highway User Went Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code		41. Highway User 1. Went around the gate 2. Stopped and then proceeded 3. Did not stop 4. Stopped on crossing 5. Other (specify) 6. Went around/thru temporary barricade (if yes, see instructions) 7. Went thru the gate 8. Suicide/Attempted suicide Code	
42. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown Code				43. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing railroad equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicles 7. Other (specify) 8. Not Obstructed Code 8			
Casualties to:		Killed		Injured		44. Driver was 1. Killed 2. Injured 3. Uninjured	
46. Highway-Rail Crossing Users 1		0		47. Highway Vehicle Property Damage (est. dollar damage) \$0		45. Was Driver in the Vehicle? 1. Yes 2. No Code	
49. Railroad Employees 0		0		50. Total Number of People on Train (include passengers and train crew)		48. Total Number of Vehicle Occupants (including driver) 0	
52. Passengers on Train 0		0		51. Is a Rail Equipment Accident / Incident Report Being Filed 1. Yes 2. No Code 2			
53a. Special Study Block Video Taken? <input type="checkbox"/> Yes <input type="checkbox"/> No Video Used? <input type="checkbox"/> Yes <input type="checkbox"/> No				53b. Special Study Block			
54. Narrative Description (Be specific, and continue on separate sheet if necessary)							
55. Typed Name and Title				56. Signature		57. Date	

NOTE: This report is part of the reporting railroad's accident report pursuant to the accident reports statute and, as such shall not "be admitted as evidence or used for any purpose in any suit or action for damages growing out of any matter mentioned in said report..." 49 U.S.C. 20903. See 49 C.F.R. 225.7 (b).

1. Name of Reporting Railroad Union Pacific Railroad Company [UP]				1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0378CA206	
2. Name of Other Railroad or Other Entity Filing for Equipment Involved in Train Accident/Incident				2a. Alphabetic Code		2b. Railroad Accident/Incident No.	
3. Name of Railroad or Other Entity Responsible for Track Maintenance (single entry) Union Pacific Railroad Company [UP]				3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. 0378CA206	
4. U.S. DOT Grade Crossing ID No. 811074G				5. Date of Accident/Incident month day year 0 3 1 1 1978		6. Time of Accident/Incident 1:00 AM <input checked="" type="checkbox"/> PM <input type="checkbox"/>	
7. Nearest Railroad Station LOS ANGELES		8. Subdivision		9. County LOS ANGELES		10. State Abbr. CA Code 06	
11. City (if in a city) LOS ANGELES			12. Highway Name or No. MONTEBELLO BLVD			Public <input checked="" type="checkbox"/> Private <input type="checkbox"/>	
Highway User Involved				Rail Equipment Involved			
13. Type C. Truck-trailer F. Bus J. Other Motor Vehicle A. Auto D. Pick-up truck G. School Bus K. Pedestrian Code B. Truck E. Van H. Motorcycle M. Other (specify) A				17. Equipment 1. Train (units pulling) 2. Train (units pushing) 3. Train (standing) 4. Car(s) (moving) 5. Car(s) (standing) 6. Light loco(s) (moving) 7. Light loco(s) (standing) 8. Other (specify) A. Train pulling- RCL B. Train pushing- RCL C. Train standing- RCL D. EMU Locomotive(s) E. DMU Locomotive(s) Code 2			
14. Vehicle Speed (est. mph at impact) 20		15. Direction (geographical) 1. North 2. South 3. East 4. West Code 1		18. Position of Car Unit in Train 1			
16. Position 1. Stalled or stuck on crossing 2. Stopped on Crossing 3. Moving over crossing Code 3		4. Trapped on crossing by traffic 5. Blocked on crossing by gates		19. Circumstance Code 1. Rail equipment struck highway user 2. Rail equipment struck by highway user Code 1			
20a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code 4				20b. Was there a hazardous materials release by Code 1. Highway User 2. Rail Equipment 3. Both 4. Neither			
20c. State here the name and quantity of the hazardous material released, if any							
21. Temperature (specify if minus) 65 °F		22. Visibility (single entry) Code 1. Dawn 2. Day 3. Dusk 4. Dark 4		23. Weather (single entry) Code 1. Clear 2. Cloudy 3. Rain 4. Fog 5. Sleet 6. Snow 1			
24. Type of Equipment (single entry) 1. Freight Train 2. Passenger Train-Pulling 3. Commuter Train-Pulling 4. Work Train 5. Single Car 6. Cut of cars 7. Yard/Switching 8. Light loco(s) 9. Maint./inspect. car A. Spec. MoW Equip. B. Passenger Train-Pushing C. Commuter Train-Pushing D. EMU E. DMU Code 7				25. Track Type Used by Rail Equipment Involved Code 1. Main 2. Yard 3. Siding 4. Industry 1		26. Track Number or Name SINGLE MAIN	
27. FRA Track Class (1-9,X) 3		28. Number of Locomotive Units 1		29. Number of Cars 9		30. Consist Speed (Recorded speed if available) R. Recorded 20 mph E. Estimated Code E	
31. Time Table Direction Code 1. North 2. South 3. East 4. West 4				32. Type of Crossing Warning Code(s) 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (specify) 12. None 01 10			
33. Signaled Crossing Warning (See reverse side for instructions and codes) Code 1			34. Roadway Conditions Code A. Dry B. Wet C. Snow/Slush D. Ice E. Sand, Mud, Dirt, Oil, Gravel F. Water (Standing, Moving)			35. Location of Warning Code 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach 1	
36. Crossing Warning Interconnected with Highway Signals Code 1. Yes 2. No 3. Unknown 3			37. Crossing Illuminated by Street Lights or Special Lights Code 1. Yes 2. No 3. Unknown 1			38. Highway User's Gender Age Code 1. Male 2. Female 2	
39. Highway User's Gender Age Code 1. Male 2. Female 2		40. Highway User Went Behind or in Front of Train and Struck or was Struck by Second Train Code 1. Yes 2. No 3. Unknown 2		41. Highway User 1. Went around the gate 2. Stopped and then proceeded 3. Did not stop 4. Stopped on crossing 5. Other (specify) 6. Went around/thru temporary barricade (if yes, see instructions) 7. Went thru the gate 8. Suicide/Attempted suicide Code 2		42. Driver Passed Standing Highway Vehicle Code 1. Yes 2. No 3. Unknown 3	
43. View of Track Obscured by (primary obstruction) Code 1. Permanent Structure 2. Standing railroad equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicles 7. Other (specify) 8. Not Obstructed 8		44. Driver was 1. Killed 2. Injured 3. Uninjured 3		45. Was Driver in the Vehicle? Code 1. Yes 2. No 1			
46. Highway-Rail Crossing Users Killed 0 Injured 0		47. Highway Vehicle Property Damage (est. dollar damage) \$450		48. Total Number of Vehicle Occupants (including driver) 1			
49. Railroad Employees 0		50. Total Number of People on Train (include passengers and train crew)		51. Is a Rail Equipment Accident / Incident Report Being Filed Code 1. Yes 2. No 2			
52. Passengers on Train 0		53a. Special Study Block Video Taken? <input type="checkbox"/> Yes <input type="checkbox"/> No Video Used? <input type="checkbox"/> Yes <input type="checkbox"/> No		53b. Special Study Block			
54. Narrative Description (Be specific, and continue on separate sheet if necessary)							
55. Typed Name and Title				56. Signature		57. Date	

NOTE: This report is part of the reporting railroad's accident report pursuant to the accident reports statute and, as such shall not "be admitted as evidence or used for any purpose in any suit or action for damages growing out of any matter mentioned in said report..." 49 U.S.C. 20903. See 49 C.F.R. 225.7 (b).

1. Name of Reporting Railroad Union Pacific Railroad Company [UP]				1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0577CA024	
2. Name of Other Railroad or Other Entity Filing for Equipment Involved in Train Accident/Incident				2a. Alphabetic Code		2b. Railroad Accident/Incident No.	
3. Name of Railroad or Other Entity Responsible for Track Maintenance (single entry) Union Pacific Railroad Company [UP]				3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. 0577CA024	
4. U.S. DOT Grade Crossing ID No. 811074G				5. Date of Accident/Incident month day year 0 5 2 0 1977		6. Time of Accident/Incident 10:00 AM <input type="checkbox"/> PM <input checked="" type="checkbox"/>	
7. Nearest Railroad Station LOS ANGELES		8. Subdivision		9. County LOS ANGELES		10. State Abbr. CA Code 06	
11. City (if in a city) MONTEBELLO			12. Highway Name or No. MONTEBELLO BLVD			Public <input checked="" type="checkbox"/> Private <input type="checkbox"/>	
Highway User Involved				Rail Equipment Involved			
13. Type C. Truck-trailer F. Bus J. Other Motor Vehicle A. Auto D. Pick-up truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (specify) Code K				17. Equipment 1. Train (units pulling) 2. Train (units pushing) 3. Train (standing) 4. Car(s) (moving) 5. Car(s) (standing) 6. Light loco(s) (moving) 7. Light loco(s) (standing) 8. Other (specify) A. Train pulling- RCL B. Train pushing- RCL C. Train standing- RCL D. EMU Locomotive(s) E. DMU Locomotive(s) Code 1			
14. Vehicle Speed (est. mph at impact)		15. Direction (geographical) 1. North 2. South 3. East 4. West Code 2		18. Position of Car Unit in Train 1			
16. Position 1. Stalled or stuck on crossing 2. Stopped on Crossing 3. Moving over crossing 4. Trapped on crossing by traffic 5. Blocked on crossing by gates Code 3				19. Circumstance 1. Rail equipment struck highway user 2. Rail equipment struck by highway user Code 1			
20a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code 4				20b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code			
20c. State here the name and quantity of the hazardous material released, if any							
21. Temperature (specify if minus) 65 °F		22. Visibility (single entry) 1. Dawn 2. Day 3. Dusk 4. Dark Code 4		23. Weather (single entry) 1. Clear 2. Cloudy 3. Rain 4. Fog 5. Sleet 6. Snow Code 1			
24. Type of Equipment Consist (single entry) 1. Freight Train 2. Passenger Train-Pulling 3. Commuter Train-Pulling 4. Work Train 5. Single Car 6. Cut of cars 7. Yard/Switching 8. Light loco(s) 9. Maint./inspect. car A. Spec. MoW Equip. B. Passenger Train-Pushing C. Commuter Train-Pushing Code 1				25. Track Type Used by Rail Equipment Involved 1. Main 2. Yard 3. Siding 4. Industry Code 1		26. Track Number or Name SINGLE MAIN	
27. FRA Track Class (1-9,X) 4		28. Number of Locomotive Units 4		29. Number of Cars 40		30. Consist Speed (Recorded speed if available) R. Recorded 30 mph E. Estimated Code E	
31. Time Table Direction 1. North 2. South 3. East 4. West Code 4				32. Type of Crossing Warning 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (specify) 12. None Code(s) 01			
33. Signaled Crossing Warning (See reverse side for instructions and codes) Code 1				34. Roadway Conditions A. Dry B. Wet C. Snow/Slush D. Ice E. Sand, Mud, Dirt, Oil, Gravel F. Water (Standing, Moving) Code			
35. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach Code 1			36. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown Code 3			37. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown Code 1	
38. Highway User's Age 1. Male 2. Female Code		39. Highway User's Gender Code		40. Highway User Went Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code		41. Highway User 1. Went around the gate 2. Stopped and then proceeded 3. Did not stop 4. Stopped on crossing 5. Other (specify) 6. Went around/thru temporary barricade (if yes, see instructions) 7. Went thru the gate 8. Suicide/Attempted suicide Code	
42. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown Code		43. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing railroad equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicles 7. Other (specify) 8. Not Obstructed Code 8					
Casualties to:		Killed		Injured		44. Driver was 1. Killed 2. Injured 3. Uninjured	
46. Highway-Rail Crossing Users 1		0		47. Highway Vehicle Property Damage (est. dollar damage) \$0		45. Was Driver in the Vehicle? 1. Yes 2. No Code	
49. Railroad Employees 0		0		50. Total Number of People on Train (include passengers and train crew)		48. Total Number of Vehicle Occupants (including driver) 0	
52. Passengers on Train 0		0		51. Is a Rail Equipment Accident / Incident Report Being Filed 1. Yes 2. No Code 2			
53a. Special Study Block Video Taken? <input type="checkbox"/> Yes <input type="checkbox"/> No Video Used? <input type="checkbox"/> Yes <input type="checkbox"/> No				53b. Special Study Block			
54. Narrative Description (Be specific, and continue on separate sheet if necessary)							
55. Typed Name and Title				56. Signature		57. Date	

NOTE: This report is part of the reporting railroad's accident report pursuant to the accident reports statute and, as such shall not "be admitted as evidence or used for any purpose in any suit or action for damages growing out of any matter mentioned in said report..." 49 U.S.C. 20903. See 49 C.F.R. 225.7 (b).